



HOT WATER SUMMARY

Date printed: 2016-Oct-18

For Dates From 2016-Sep-18 Through 2016-Oct-18

Locations: Hampton Inn - Tamarac, FL

Nests: Domestic HW

Groups: Loop 1





OTO

Hampton Inn - Tamarac, ...
Location

DRV80
DRV

Hampton Inn, Tamarac, ...
Equipment ID

Overall Diagnostics

As calculated from 8,900 system checks.

Setpoint		125 °F	
Mixed Water Supply	112 °F	124 °F	128 °F
System Return	111 °F	119 °F	121 °F
Hot Water Supply	112 °F	139 °F	144 °F
	Minimum	Average	Maximum


Service Life




2009-Apr-28
Commissioned Date

2730
Days In Service


-904
Warranty Days Remaining

System Performance Record





167 Alerts



Description	Count	% of Total
Hot Water Supply Low	104	62%
Hot Water Supply Below Setpoint	58	35%
Mixed Water Supply Low	5	3%
	167	